

# Belzona Repairs Conveyor Belt

ID: 9213


Industry: *Mining & Quarrying*  
Application: *SHM-Solids Handling Machinery*

Customer Location: *Botswana*  
Application Date: *August 2015*

Substrate: *Rubber*  
Products: *Belzona 2131 (D & A Fluid Elastomer), Belzona 2911 (Elastomer QD Conditioner), Belzona 9111 (Cleaner Degreaser)*

## Problem

*A 10 meter section of the top layer rubber on a belt wore out.*



Condition of belt



After application

## Application Situation

The client needed a fast solution to assist them until the next outage.

## Application Method

After abrading the belt, it was cleaned and degreased with Belzona 9111. A thin layer of Belzona 2911 Conditioner was applied to the damaged section.

Once the conditioner was touch dry, Belzona 2131 was applied and allowed to fully cure.

## Belzona Facts

Instead of shutting the entire section down to replace the belt, Belzona saved the client time and money.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve