

Food manufacturing facility has Belzona repair End Quote refrigerator floor

ID: 9270

Industry:	Food & Drink	Customer Location:	Oklahoma City, Oklahoma
Application:	FPA-Floor Problem Areas	Application Date:	February 2024
Substrate:	Concrete		
Products:	Belzona 4154 (Bulkfill Resin), Belzona 5811 (Immersion Grade)		

Problem

The floor in this refrigerator has been sitting on sub zero temperatures for 25 years. Constant freezing and unfreezing has left the concrete floor in very bad condition. In some areas it had up to two inches of concrete loss.



Area prior to application Commencement of application Belzona 5811 applied to area Application completed

Application Situation

The only down time the customer had was over a long weekend. This floor was not suitable for food refrigeration and had to be taken care of as soon as possible. The preparation cleaning resurfacing and coating of this floor was done in three days. The customer is extremely happy with the outcome of the floor and has three more refrigeration units to be done shortly with Barzona repair system.

Application Method

The Belzona products were applied by hand

Belzona Facts

Belzona is the only coating supplier that is trusted by this food facility. Over the last few years multiple repairs has been done to this facility using only Belzona products.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

