

# BELZONA SEALS WAREHOUSE FLOOR

ID: 934

Industry: Buildings & Structures

Application: FPA-Floor Problem Areas

Substrate: Concrete floor with block walls

Products: \* Belzona® 4131 (Magma Screed) ,  
\* Belzona® 4251 (Magma Flex Fluid) ,  
\* Belzona® 3121 (MR-7) ,

Customer Location: Chemical Producer, Pennsylvania USA

Application Date: February 2004

## Problem

Chemical spills however quickly cleaned up could contaminate ground-water. Facility near two major rivers. Floor had many cracks and gaps around wall to floor detail.



## Photograph Descriptions

- \* Floor to wall joint before sealing ,
- \* Sealing warehouse floor-expansion joints ,
- \* Sealing joint around perimeter ,
- \* Repaired/sealed cracks with Belzona® 4131 ,

## Application Situation

Major Industrial gas/chemical producer has warehouse full of 55 gallon drums, with no containment for spills.

## Application Method

Application was carried out following Belzona Know-How System Leaflets FPA-6 and TCC-15. Cracks were chased out before being filled and sealed.

## Belzona Facts

Customer satisfied with other work at facility and inspection in March 2007 showed all Belzona to be in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve