

BELZONA SEALS WAREHOUSE FLOOR

ID: 934

Industry: Buildings & Structures

Application: FPA-Floor Problem Areas

Substrate: Concrete floor with block walls

Products: * Belzona® 4131 (Magma Screed) ,
* Belzona® 4251 (Magma Flex Fluid) ,
* Belzona® 3121 (MR-7) ,

Customer Location: Chemical Producer, Pennsylvania USA

Application Date: February 2004

Problem

Chemical spills however quickly cleaned up could contaminate ground-water. Facility near two major rivers. Floor had many cracks and gaps around wall to floor detail.



Photograph Descriptions

- * Floor to wall joint before sealing ,
- * Sealing warehouse floor-expansion joints ,
- * Sealing joint around perimeter ,
- * Repaired/sealed cracks with Belzona® 4131 ,

Application Situation

Major Industrial gas/chemical producer has warehouse full of 55 gallon drums, with no containment for spills.

Application Method

Application was carried out following Belzona Know-How System Leaflets FPA-6 and TCC-15. Cracks were chased out before being filled and sealed.

Belzona Facts

Customer satisfied with other work at facility and inspection in March 2007 showed all Belzona to be in perfect condition.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve