

Reviving Gray and Black Tanks Inside a Marine Vessel with Belzona Solutions

ID: 9343

Industry: Marine
Application: TCC-Tanks and Chemical Containment Areas

Customer Location: Ontario, Canada
Application Date: September 2023

Substrate: Cast Iron

Products: Belzona 1111 (Super Metal), Belzona 5811 (Immersion Grade)

Problem

The gray and black tanks inside the marine vessel were suffering from coating failure and corrosion issues. The main flange also required repair from wear.



Tanks before surface preparation.



After surface preparation.



Gray Tank After application of two coats of Belzona 5811.



Black Tank After application of two coats of Belzona 5811.

Application Situation

The gray and black tanks inside a marine vessel were suffering from coating failure and corrosion issues and the main flange from wear.

Application Method

After solvent cleaning, and then with the use of a power tool, tank internal surfaces were prepared to SP11. Flanges were also rebuilt using Belzona 1111. Two coats of Belzona 5811 were then applied.

Belzona Facts

Adequate technical support was given to ensure application was carried out according to standards.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

Copyright © Belzona International Limited 2025