

Belzona SuperWrap II restores pipe integrity

ID: 9360

Industry: Chemical & Petrochemical
Application: VPF-Valves, Pipes and Fittings
Substrate: Carbon steel
Products: Belzona 1212, Belzona 1981 (SuperWrap II)

Customer Location: United Kingdom
Application Date: February 2024

Problem

A section of cooling water pipework was corroded through wall. A repair was required to prevent any leaks occurring and to restore strength to the pipework.



Corroded pipe section



Completed repair with Belzona 1981 SuperWrap 2 installed

Application Situation

Replacement of the pipework is due, this repair is to keep the equipment running until that time.

Application Method

The area was cleaned & roughened using angle grinders. Belzona 1212 was then applied to fill any large pits & to fair the surface. Four overlapping wraps of Belzona SuperWrap II were then applied & consolidated with Belzona 9382

Belzona Facts

This repair was completed in one day with minimal disruption to the surrounding plant operations. The high strength of the system will ensure pipe integrity even if corrosion continues to occur on the underlying metal.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve