

BELZONA REFURBISHES LABORATORY WORKTOPS

ID: 937

Industry: Water / Wastewater
Application: WPA-Wall Problem Areas
Substrate: unknown
Products: Belzona® 5811 (Immersion Grade)

Customer Location: State Health Dept.
Application Date: March 2005

Problem

Severely degraded counter tops needed to be resurfaced with a chemically resistant coating.



Photograph Descriptions

* Sink in lab before work , * Fume cupboard before work , * Sink after coating , * Counter top after coating ,

Application Situation

State Health Dept was building new facility and needed to extend life of existing facility lab counter tops

Application Method

Application carried out in accordance with modified Belzona System leaflet FPA-3. Special care was taken to clean sand the surfaces. Belzona® 5811 applied over-thickness with a trowel to create a self levelling coat.

Belzona Facts

Saved tens of thousands of dollars on replacements. In December 2007 Facilities Manager reports all is well, no complaints from workers.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2024