

Sealing of leaks to SF6 Gas Circuit Breaker in large substation

ID: 9380

Industry: Power
Application: GSS-Gaskets, Seals and Shims
Substrate: Other
Products: Belzona 7311

Customer Location: Newark, Nottinghamshire
Application Date: April 2024

Problem

SF6 leaking from joints and bolts



Prepare area with emery paper/ wire brush making surface area as rough as possible.



Initial wetting out with a short bristled brush to coat all target areas



Cover nuts/bolts with belzona filled caps
Wrap with bandage around whole area, overlapping and patching where necessary.



Build up Belzona product, ensuring no air pockets remain. Product given a week to cure before 5 bar restored to the Gas Circuit Breaker

Application Situation

An effective repair was made to the de-gassed breaker.

The team received detailed training from the Senior Area Sales Engineer and felt confident enough to effect the repair without using outside help

Following the training, they were able to carry out the repair at a time convenient to them and within the allowed outage of the equipment

Application Method

Isolate and de-gas

Abrade the target area as much as possible

Wet out all target areas with mixed Belzona 7311

Wet out the Belzona 9341 reinforcing sheet

Fill bolt caps and cover all bolts, then apply reinforcing sheet

Build up with Belzona 7311 to encapsulate all possible leaking sites

Allow to cure then introduce gas back to 5 bar working pressure

Belzona Facts

SF6 has 23,500 time more damage potential to the world's environment than CO2. This was carried out as a best effort

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve