

Concrete Floor Repairs

ID: 9406

Industry: *General Industry* **Customer Location:** *Southwestern Ontario*
Application: *FPA-Floor Problem Areas* **Application Date:** *April 2023*
Substrate: *Concrete*
Products: *Belzona 4111 (Magma-Quartz), Belzona 4911 (Magma TX Conditioner), Belzona 9111 (Cleaner Degreaser)*

Problem

The customer was experiencing that their steel wheel conveyor system due to heavy loads were wearing grooves into the concrete floor.



Floor area showing where the grooves have been repaired on this conveyor.

Floor area showing where the grooves have been repaired on this conveyor.

Floor area showing where the grooves have been repaired on this conveyor.

Application Situation

Concrete floor at the moving conveyor production area was in need of repairs and the customer was in need of a quick fix.

Application Method

Application was carried out using the Belzona System Leaflet FPA-1

Belzona Facts

The Belzona customer is very pleased with the results of the products used, they are scheduling to repair more floor areas at the next plant shutdown.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

