

# BELZONA STEP NOSING REPAIR


ID: 942

Industry: Buildings & Structures  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: Belzona® 4111 (Magma Quartz)<div>Belzona® 4411 (Granogrip)</div>

Customer Location: Racecourse, Liverpool, England  
Application Date: March 2007

## Problem

Porters had been bouncing beer barrels down the steps from the bar situated on the floor above. This was damaging the concrete step nosings.



## Photograph Descriptions

\* Steps showing signs of damage , \* Close up of damage , \* Steps repaired , \* Close up of repair ,

## Application Situation

Damaged step nosings.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & -8.

## Belzona Facts

Belzona was chosen due to its high bond strength, impact resistance and hard wearing non-slip surface proven in similar environments.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve