

Belzona 4111 Makes For A Smooth Floor

ID: 9455

Industry: Steel & Metal Processing

Customer Location: Washington

Application: FPA-Floor Problem Areas


Application Date: February 2021

Substrate: Concrete

Products: Belzona 4111 (Magma-Quartz), Belzona 4911 (Magma TX Conditioner)

Problem

This older metal casting facility had a lot of damaged areas on their concrete floor.



One of the damaged areas in a doorway.



Damaged doorway area repaired.



Showing several areas of damage near a machine.



Several damaged areas repaired.

Application Situation

With full time operation and only one down day, doing floor repair is a difficult task as they need a material that can be walked on in less than one day of application. Belzona 4111 was the perfect solution. Due the higher temperature in the foundry, the Belzona 4111 was ready for pedestrian traffic in 4 hours.

Application Method

The damaged concrete areas were prepped with a hand grinder and wire wheel to remove all loose material and roughen the surface. The Belzona 4911 conditioner was applied with a short bristled brush, and the Belzona 4111 was applied by hand, pushed firmly into the repair areas, and finished with a steel trowel.

Belzona Facts

Other concrete repair materials had been tried, and all had failed. The damaged areas were causing trip hazards, and making it difficult to push wheeled carts over the floor. The Belzona 4111 solution allowed the customer to address many different areas from small divots to large cracks and areas where previous walls had been removed leaving deep areas of damage. Being able to do the application during their one day shutdown and return to service well before the plant began to operate was a huge positive for their maintenance team. They also liked the simplicity of the application process, and that there is no chemical/solvent smell when mixing and applying the Belzona materials. The ease of application also allows them to do further concrete repairs as needed on a more regular basis. Checking back with the customer 6 months later showed all of these repairs in perfect condition, and many other areas that they have repaired themselves since.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve