

Belzona Helps Make Quality Chips

ID: 9457


Industry: *Pulp & Paper*
 Application: *SHM-Solids Handling Machinery*

Customer Location: *Washington*
 Application Date: *February 2015*

Substrate: *Carbon steel*
 Products: *Belzona 1811 (Ceramic Carbide)*

Problem

The pockets where the chipper knives are mounted were wearing out.



The chipper disk.



One of the pockets ready for application.



Starting the application.



Application completed.

Application Situation

The pockets located behind the chipper knives wear back over time. This creates irregular wood chips, which in turn lowers the quality of the chips that the paper mills purchase. Applying Belzona 1811 to protect against the wear lengthens the life of the blade and allows the mill to produce consistent high quality wood chips.

Application Method

The application surface was prepped by grit blasting, solvent washed, and the Belzona 1811 was applied using the mixing knife, applicator, and by hand. Once the material was firm enough, the surface was smoothed down by hand using soapy water, creating a fine smooth finish.

Belzona Facts

Belzona 1811 is perfect for repairing and extending the life of a chipper disk. It protects the steel, but also due to the carbide chips in the material, as the chips pass through, the wood leaves behind a layer of wood fiber on the exposed ceramic chips. This creates

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
 FS 695214
 ISO 14001:2015
 EMS 695213

Belzona products are
 manufactured under an ISO
 9000 Registered Quality
 Management System.

www.belzona.com

BELZONA
 Repair • Protect • Improve

a bed of wood fiber to further protect the pocket, and further extend the life of the chipper disk, all while producing consistently dependable wood chips that the pulp mill will pay more for as it makes for better paper products. This application also reduces the amount of wood chip jams in the chipper disk, which means less unnecessary shutdowns.

Regular inspections showed minimal wear of the Belzona 1811, much less than the original steel had, and did not require any further attention for 4 years. At that time, as a preventative measure, some additional Belzona 1811 was added to the original material applied in 2015.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

