

BELZONA RESTORED THE ERODED TRANSPORT VESSEL TAIL PIPE

ID: 9473

Industry: Customer Location: MESAEED, QATAR Marine

Application: SOS-Ships and Offshore Structures Application Date: July 2023

Substrate: Aluminum

Products: Belzona 1311 (Ceramic R-Metal), Belzona 1321 (Ceramic S-Metal)

Problem

Corrosion-erosion damaged lower half of the tail pipe due to stationary submerged in seawater for 3 years.









BEFORE SURFACE PREPARATION SHOWING THE EXTENT OF DAMAGE DUE TO METALLIC EROSION.

AFTER SURFACE PREPARATION ALL DAMAGED AREA WAS BY GRIT BLASTING EXPOSING **DEEP PITTING AND METAL**

REBUILT USING BELZONA 1311.

COMPLETED APPLICATION.

Application Situation

Severe corrosion pitting on lower half of the Tail Pipe which needs to be rebuilt to restore the original state and requires ceramic protective coating for future prevention against erosion attack.

Application Method

The Belzona product was applied in accordance with Belzona System Leaflet SOS-1

Manual application using stiff bristle brush and provided plastic applicator to rebuild the eroded areas and to apply protective ceramic coating.

Belzona Facts

Belzona 1311 is a High performance Abrasion Resistant Rebuilding Grade.

LOSS.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are FS 695214 manufactured under an ISO ISO 14001:2015 9000 Registered Quality EMS 695213 Management System.

www.belzona.com



| Belzona 1321 is a High Performance Corrosion/ Erosion Resistant Ceramic Coating Grade. One year after the application, the client provided feedback that the equipment is still in good working condition. |
|---|
| One year after the application, the client provided reedback that the equipment is still in good working condition. |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |
| |

ISO 14001:2015 EMS 695213

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO 9000 Registered Quality Management System.



www.belzona.com