

Employee Walkway

ID: 9486

Industry: General Industry Customer Location: Clinton Tennessee
Application: FPA-Floor Problem Areas Application Date: June 2024
Substrate: Concrete
Products: Belzona 5231 (SG Laminate), Belzona 9221 (Surefoot Aggregate White)

Problem

The customer had tried 2 other options. They tried staining the concrete without success. They tried a local hardware store product without success. Then called Belzona.



This is the walkway before. It is very worn looking and it's only been down a month.

Belzona 5231 and Belzona 9211 applied.

Application Situation

The customer was not happy with the results of the first 2 tries. The Engineering manager was familiar with Belzona but was trying to find a cheaper option.

Application Method

Belzona 5231 was applied in 2 coats with a small amount of 9221. The 5231 was rolled onto the floor. The 9221 was hand sprinkled.

Belzona Facts

Belzona was chosen because of the long-term results. Two cheaper options were tried without satisfactory results.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve