

Belzona 1341 Solution on Brass Impeller

ID: 9515

Industry: Water / Wastewater
Application: CEP-Centrifugal Pumps
Substrate: Bronze
Products: Belzona 1341 (Supermetalgilde)

Customer Location: Oklahoma City
Application Date: August 2024

Problem

Customer was looking for a protective coating for the impeller. Belzona was required to provide a suitable solution.



Look at the impeller after surface preparation was completed.



Impeller after the 1st coat with Belzona 1341.



2nd coat of Belzona 1341.



Final inspection completed.

Application Situation

Application with Belzona 1341 was completed within a day, reducing downtime.

Application Method

Application of Belzona 1341 was done by hand as per Instructions for Use.

Belzona Facts

We completed five additional pumps for this customer, proving Belzona solutions are reliable.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

Copyright © Belzona International Limited 2024


BELZONA[®]
Repair • Protect • Improve