

# Belzona floor repair

ID: 9517

Industry: Food & Drink

Customer Location: Oklahoma

Application: FPA-Floor Problem Areas



Application Date: February 2024

Substrate: Concrete

Products: Belzona 4111 (Magma-Quartz), Belzona 5811 (Immersion Grade)

## Problem

*This floor was extremely slippery and was worn down form years of use*



The floor was prepped with hand tools, cleaned and then repaired whit Belzona 4111.

First coat of Belzona 5811 black on floor for protection

Second and final coat of Belzona 5811

The floor 2 weeks after Application

## Application Situation

When the floor was done, the floor was grinded and cleaned by hand and then rollers and brushes were used to apply the Belzona product to the floor.

## Application Method

4inch grinders  
epoxy rollers  
brushes  
acetone  
type and buckets

## Belzona Facts

This customer has used Belzona 5811 and 4111 for years. All of the applications that has been done is still in service

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve