

Containment Pond

ID: 9533

Industry: *General Industry*
Application: *TCC-Tanks and Chemical Containment Areas*
Substrate: *Concrete*
Products: *Belzona 3121 (MR7), Belzona 5231 (SG Laminate)*


Customer Location: *Dayton TN*
Application Date: *June 2023*

Problem

The containment area was very old and was suffering issues with cracking. The containment area was not in use but looked really bad for the inspectors of the plant. They wanted to save the area in case they decided to use it.



Containment area before restoration.



Cracks on the side of the containment area



Cracks being repaired with Belzona 3121



Containment area finished with two coats of Belzona 5231

Application Situation

To remove or replace the containment are would have been very expensive as well as down time. We were able to do the project in one week.

Belzona cost was \$ 20,382.00

Application Method

The contractor pressure washed the area and used a pump to remove the water. The cracks were repaired with Belzona 3121 and reinforcing cloth 9331. Then two coats of Belzona 5231 were applied.

Belzona Facts

Belzona was the cheapest option. This customer sent me a message on LinkedIn he was looking for the closest Belzona rep and it was me. He had used Belzona in the past at a different location in another state.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve