

Belzona repairs tile lining

ID: 9562

Industry: *Pulp & Paper*

Customer Location: *Castlegar*

Application: *SHM-Solids Handling Machinery*

Application Date: *September 2024*

Substrate: *Carbon steel*

Products: *Belzona 1321 (Ceramic S-Metal), Belzona 1812 (Ceramic Carbide FP)*

Problem

Holes in multiple locations due to missing tiles



One of many holes



Holes repaired and tiles installed with grout



Completed application

Application Situation

Emergency repair of a flat back chip chute elbow. Chips were piling up outside of the equipment causing fire hazard.

Application Method

Surface mechanically prepared with hand tools, tiles bonded and grouted with Belzona

Belzona Facts

Job completed in under 6 hours for an emergency repair. Major cost saving from operational standpoint and downtime savings.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve