

# Drive roller for a conveyor belt

ID: 9624

Industry: *Mining & Quarrying*

Customer Location: *Oklahoma city*

Application: *ENC-Engines and Casings*


Application Date: *October 2024*

Substrate: *Carbon steel*

Products: *Belzona 2211 (MP Hi-Build Elastomer), Belzona 5811 (Immersion Grade)*

## Problem

*The customer wanted to refurbish their old drive motor conveyor pulley and have it resurfaced with Belzona*



Belzona first coat on pully



Demarcation on pully for Belzona application



Belzona 2211 first coat



Belzona 2211 second coat

## Application Situation

From start to finish the application took 1 day.

The most time was spent letting the Belzona 5811 set up.

## Application Method

The application was done by hand using 2-inch brushes and Belzona applicators.

## Belzona Facts

This job can be done for a 10% of the cost for a new roller

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve