

# BELZONA DRAIN COVERS


ID: 966

Industry: General Industry  
Application: FPA-Floor Problem Areas  
Substrate: Stainless Steel  
Products: Belzona® 4111 (Magma Quartz)

Customer Location: Bakery, West Midlands, UK  
Application Date: May 2008

## Problem

Existing covers and surrounds badly deteriorated due to corrosion and chemical attack. rapid solution required due to continuous production schedule on site. Conventional steel/concrete covers do not have adequate resistance.



## Photograph Descriptions

\* Fabricated drain covers in Steel being conditioned , \* Bulk out Belzona® 4111 being applied , \* Bulk out Belzona® 4111 finished ready to be topped off with Belzona® 4111 , \* Finished cover ready for transport and installation on site ,

## Application Situation

Deterioration of drain covers and surrounds

## Application Method

Application was carried out in accordance with a modified Belzona Know-How System Leaflet FPA-1. New drain covers were manufactured off-site from Stainless Steel and infilled with Belzona® 4111. On site bedded into Belzona® 4111 and damaged surrounds rebuilt.

## Belzona Facts

The work was carried out during the agreed window in a professional manner with no disruption to the production processes. Solution provides long term solution.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

Copyright © Belzona International Limited 2024