

# Concrete Stairs saved from further dilapidation.

ID: 9696

Industry: Local Authorities & Municipalities  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: Belzona 4111 (Magma-Quartz)

Customer Location: Ontario  
Application Date: September 2014

## Problem


Stairs was experiencing cracks along the railing pillar and was on the verge of falling apart.




Cracks on stairs before repair.



Further cracks .



After surface preparation.



Stairs after repair.

## Application Situation

Concrete stairs was on the verge of falling apart due to stress from the railings and customer wanted a fast repair that would enable the area opened to the public in the fastest way.

## Application Method

The weak parts of the concrete stairs was removed and vacuumed. The areas were subsequently rebuilt with Belzona 4111.

## Belzona Facts

Belzona repair was carried out and the area opened to for public use in matter of days.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve