

Hospital Drain

ID: 9706

| | | | |
|--------------|--|--------------------|-------------|
| Industry: | Buildings & Structures | Customer Location: | Columbia TN |
| Application: | FPA-Floor Problem Areas | Application Date: | August 2024 |
| Substrate: | Concrete | | |
| Products: | Belzona 4111 (Magma-Quartz),Belzona 5231 (SG Laminate) | | |

Problem
Drain was leaking in patients room.



Drain condition before repair with Belzona

Drain condition before repair with Belzona

Final application of Belzona solution

Final application of Belzona solution

Application Situation

Customer was planning on replacing the concrete and drain before I gave them the option to repair it.

Application Method

Concrete was prepared with hand tools and cleaned before doing the repair.

Belzona Facts

Belzona was cheaper and less time consuming than to replace the old concrete and drain

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

| | |
|----------------|---------------------------|
| ISO 9001:2015 | Belzona products are |
| FS 695214 | manufactured under an ISO |
| ISO 14001:2015 | 9000 Registered Quality |
| EMS 695213 | Management System. |

www.belzona.com

