

Frito Lay Shaft Repair

ID: 9712

Industry: *General Industry*
Application: *SHM-Solids Handling Machinery*

Customer Location: *Fayetteville TN*
Application Date: *October 2017*

Substrate: *Carbon steel*
Products: *Belzona 1111 (Super Metal)*

Problem

Customer has a shaft that was worn due to bearing failure.



Shaft was worn out.



Application of Belzona 1111



Sanding out for final touch of the repair.



Application completed

Application Situation

Customer needed a repair done as soon as possible.

Application Method

Shaft was prepared and cleaned Belzona 1111 was applied

Belzona Facts

Customer chose Belzona to return back to service in a timely manner.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve