

# Frito Lay Shaft Repair

ID: 9712


Industry: General Industry  
Application: SHM-Solids Handling Machinery

Customer Location: Fayetteville TN  
Application Date: October 2017

Substrate: Carbon steel  
Products: Belzona 1111 (Super Metal)

## Problem

Customer has a shaft that was worn due to bearing failure.



Shaft was worn out.



Application of Belzona 1111



Sanding out for final touch of the repair.



Application completed

## Application Situation

Customer needed a repair done as soon as possible.

## Application Method

Shaft was prepared and cleaned Belzona 1111 was applied

## Belzona Facts

Customer chose Belzona to return back to service in a timely manner.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve