

# Bonnell Sump

ID: 9713

Industry: General Industry

Application: FPA-Floor Problem Areas

Substrate: Concrete

Products: Belzona 4111 (Magma-Quartz), Belzona 4341 (Magma CR4)

Customer Location: Gordonsville TN

Application Date: December 2024

## Problem

Customer had a leaking sump and damaged concrete.



Application area.



Application in progress.



Completed application.

## Application Situation

Customer has us to come in every December to recoat and add more areas in the plant.

## Application Method

Contractor has to prepare the concrete and follow guidelines for air quality and confine space. Belzona 4111 was used to rebuild the concrete and Belzona 4341 to provide chemical resistance protection.

## Belzona Facts

We are helping to keep the plant safe from leaks next to impossible to replace all of the sumps and troughs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

Copyright © Belzona International Limited 2025