

Concrete Chemical Trough Protection with Belzona

ID: 9714

Industry: General Industry

Customer Location: Gordonsville TN

Application: TCC-Tanks and Chemical Containment Areas

Application Date: December 2024

Substrate: Concrete

Products: Belzona 1111 (Super Metal), Belzona 4341 (Magma CR4)

Problem

Trough was damaged due to age and acid attack. Customer required a Belzona solution.



Overview of repair area.

Overview after surface preparation was completed.

Application in progress.

Completed application.

Application Situation

Customer needed a quick solution. Could not afford to replace concrete due to downtime .

Application Method

Contractor had to naturalize and clean concrete then repair before coating. They had to monitor the air quality. Belzona 1111 was used to rebuild the areas and Belzona 4341 to provide chemical resistance protection.

Belzona Facts

Customer has us to recoat and continue adding more projects every December.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve