

BELZONA MEMBRANE TO THE RESCUE


ID: 979

Industry: Buildings & Structures
Application: RPA-Roof Problem Areas
Substrate: Felt
Products: * Belzona 3131 (WG Membrane) ,

Customer Location: Hotel, Edinburgh, Scotland
Application Date: December 2007

Problem

Water penetrating gutter joints due to weight of water on the joints. Owner required immediate repairs to prevent disruption to business.



Photograph Descriptions

- * View of the "tired" and uncoated roof ,
- * Area where water was penetrating ,
- * Completed gutter, the main problem area ,
- * Completed Belzona application ,

Application Situation

Felt roof over hotel restaurant.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet RPA-1 and RPA-6.

Belzona Facts

The customer was impressed with the fact that repairs were completed without causing a major disruption or noise to restaurant

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com



guests. The application was completed during the cold month of December.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

