

BELZONA LINING OF WATER TANK

ID: 983

Industry: General Industry

Customer Location: Food manufacturer, UK

Application: TCC-Tanks and Chemical Containment Areas

Application Date: September 2007

Substrate: Steel

Products: Belzona® 5811DW (DW Immersion Grade)<div>Belzona® 1111 (Super Metal)</div>

Problem

Over a period of years the interior lining of the tank had deteriorated to a point where it was both leaking and affecting the water quality.



Photograph Descriptions

* Tank showing method for disposing of waste and debris from within tank , * Top of Tank showing Hoist for vacuation of material and personnel , * Internal of Tank prior to Coating , * Internal of Tank after coating ,

Application Situation

Company involved in manufacture of Margarine. As part of this process they use water drawn from a Bore Hole which is stored in a steel tank with a capacity 84,000 litres

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

Belzona Facts

Belzonas ability to provide a turn key solution through an Authorised contractor and approved materials within a very tight time frame won the business.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Copyright © Belzona International Limited 2025