

# Knock out drum

ID: 9876

Industry: Oil & Gas  
Application: TCC-Tanks and Chemical Containment Areas  
Substrate: Carbon steel  
Products: Belzona 1511 (Super HT-Metal)

Customer Location: Oklahoma  
Application Date: May 2025

## Problem

The knock out drum had pitting on 55% of the tank. Sherwin Williams Company did not have a pitting filler.




Looking into the Knock out drum for the outside .



Contractor applying Belzona 1511



Looking into the Knock out drum for the outside Contractor applying Belzona 1511



Looking into the Knock out drum for the outside Contractor applying Belzona 1511

## Application Situation

Belzona 1511 had to be ship on a hotshot after Sherwin Williams Company drop the ball and did not supply the product.

## Application Method

The Application was don by hand

## Belzona Facts

Sherwin Williams Company did not have the product in die country and it was a 4 week del.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

Oklahoma and Miami had the stock and did the job.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

[www.belzona.com](http://www.belzona.com)

