

Knock out drum

ID: 9876

Industry: Oil & Gas
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Carbon steel
Products: Belzona 1511 (Super HT-Metal)

Customer Location: Oklahoma
Application Date: May 2025

Problem

The knock out drum had pitting on 55% of the tank. Sherwin Williams Company did not have a pitting filler.



Looking into the Knock out drum for the outside .



Contractor applying Belzona 1511



Looking into the Knock out drum for the outside Contractor applying Belzona 1511



Looking into the Knock out drum for the outside Contractor applying Belzona 1511

Application Situation

Belzona 1511 had to be ship on a hotshot after Sherwin Williams Company drop the ball and did not supply the product.

Application Method

The Application was don by hand

Belzona Facts

Sherwin Williams Company did not have the product in die country and it was a 4 week del.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve

Oklahoma and Miami had the stock and did the job.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

