

# Hi chem Pump feet protection

ID: 9897

Industry: *General Industry*  
Application: *CEP-Centrifugal Pumps*  
Substrate: *Carbon steel*  
Products: *Belzona 4311 (Magma CR1)*

Customer Location: *Oklahoma city*  
Application Date: *March 2025*

## Problem

*The Pump base was being eaten up by a combination of chemicals in their system in only 3 months.*



Pump pedestals being blasted



Pump pedestals first coat with Belzona 4311



Pump pedestals Close up first coat



Pump pedestals second coat

## Application Situation

The pump basis had to be done on-site at the customers premises.  
Belzona was the only option for them.

## Application Method

Blasting, hand application

## Belzona Facts

The pump basis has not been for several months

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve

Copyright © Belzona International Limited 2025