

High Visibility Marking for fall Hazard

ID: 9942

Industry:	Water / Wastewater	Customer Location:	Victoria, BC
Application:	FPA-Floor Problem Areas	Application Date:	June 2025
Substrate:	Composite		
Products:	Belzona 5231 (SG Laminate), Belzona 9231 (Surefoot Aggregate)		

Problem

The customer recognized a safety hazard atop wastewater tanks. When workers are present they must walk atop these tanks and the potential to trip and fall could result in a 4-5M fall. High visibility line markings were needed



High visibility markings identifying fall hazard



Clean lines, 3 coats total were applied



Text application using custom stencil



A total 7 tank lids were completed

Application Situation

Belzona BC has a long standing history of success with the plant and our products are recognized as the #1 choice for such applications.

Application Method

The areas were masked off in neat and tidy lines and a template was made indicating 'FALL HAZARD' as specified by the safety teams. Belzona 5231 was applied by brush and roller and Belzona 9231 Surefoot Aggregate was broadcasted to rejection. A final coat of Belzona 5231 was applied as a top coat.

Belzona Facts

Competitor high visibility products had previously been applied and lasted less than ONE year.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

