

# Belzona protects Containment Area in a Wastewater plant

ID: 9947

Industry: Water / Wastewater  
Application: TCC-Tanks and Chemical Containment Areas  
Substrate: Concrete  
Products: Belzona 5815

Customer Location: Victoria, BC  
Application Date: June 2025

## Problem

A recent leak in the containment area had water penetrating through cracks in the concrete into an electrical room below.



Photo of containment area with storage tanks removed



Application in progress



View of containment area



Finished application

## Application Situation

A flexible coating was needed to bridge cracks and provide long term protection

## Application Method

The concrete was ground using diamond cup grinders with hepa-vac systems. Two coats of Belzona 5815 were applied by brush & roller.

## Belzona Facts

As the trusted coating supplier / contractor for the plant, Belzona was chosen from past successes in the plant.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

Copyright © Belzona International Limited 2025

  
**BELZONA**  
Repair • Protect • Improve