

# Belzona solution for failed expansion joints


ID: 9951

Industry: Buildings & Structures  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: Belzona 4521 (Magma-Flex Fluid), Belzona 4911 (Magma TX Conditioner)

Customer Location: Worksop  
Application Date: April 2019

## Problem

Repeated failed expansion joints meant the client needed to rethink the approach for a solution which would be durable and lasting.



Area is prepared and foam backer rod is placed at the correct depth



Joint prepared and 4521 being applied



Pouring in the Belzona 4521



Completed works showing the Belzona 4521 still in it's intended location

## Application Situation

On many occasion, other materials, mainly the general polysulphides had been offered as a solution. The client needed a durable solution

## Application Method

All target areas were cleaned and vacuumed, then masked along the sides to give clean lines

A foam backer rod was inset into the joint at a depth of half that of the joint's width

Belzona 4911 was applied to all target areas

The Belzona 4521 was mixed and applied in accordance with the IFU

This was then poured into the joint, smoothed over, masking removed and left to cure

## Belzona Facts

The Belzona 4521 held it's place, giving it ample time to cure, giving a long lasting and robust solution

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve